



## EQUIPMENT LIST

### CNC MILLS

#### HAAS VF-2

X-Axis Travel 30"

Y-Axis Travel 16"

Z-Axis Travel 22"

#### Doosan DNM5700

X-Axis Travel 40"

Y-Axis Travel 20"

Z-Axis Travel 20"

#### HAAS VF-3

X-Axis Travel 40"

Y-Axis Travel 20"

Z-Axis Travel 25"

#### Kitamura MyCenter

##### H400 Horizontal

X-Axis Travel 24"

Y-Axis Travel 20"

Z-Axis Travel 20"

### CNC LATHES

#### Daewoo Puma 200MS

2.5" spindle bore

8" C-Axis

#### Doosan Lynx 220

2.5" spindle bore

2Axis

### MANUAL MACHINES

Hardinge Tool Room Lathe

Bridgeport Manual Mill

*Please send RFQs to [RFQ@on-pointmachining.com](mailto:RFQ@on-pointmachining.com)*

---